

Preliminary Report on the Serious Incident involving an Embraer 145LR aircraft operated by Rano Air Limited with nationality and registration marks 5N-BZY, which occurred en route to Saddiq Abubakar III International Airport (DNSO), Sokoto State, on 29 June 2025

| | |
|--|--|
| Operator: | Rano Air Limited |
| Aircraft type and model: | Embraer 145LR |
| Manufacturer: | Embraer, Brazil |
| Year of manufacture: | 2002 |
| Nationality and registration marks: | 5N-BZY |
| Serial number: | 145628 |
| Location: | En route Saddiq Abubakar International Airport, Sokoto State |
| Date and Time: | 29 June 2025 at about 15:33 h <i>(All times in this report are local time, equivalent to UTC+1 unless otherwise stated)</i> |



INTRODUCTION

The Nigerian Safety Investigation Bureau (NSIB) was notified of the incident by the operator on June 29, 2025. Investigators were dispatched to Sokoto the next day. Post-occurrence assessments commenced under the provisions of Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 2023 and Annex 13 to the Convention on International Civil Aviation.

This Preliminary Report outlines the initial facts, discussions, and findings related to the incident. It includes information gathered from witness statements, the ATC transcript, and a preliminary inspection of the aircraft.

The report presents the current status of the notification's processing. Its content may still change and does not necessarily bind the conclusions published in the investigation's Final Report.

The investigation is ongoing.



1.0 FACTUAL INFORMATION

1.1 History of the flight

On 29 June 2025, an Embraer 145LR aircraft, operated by Rano Air Limited with nationality and registration marks 5N-BZY, was scheduled to conduct a passenger flight from Nnamdi Azikiwe International Airport (DNAA), Abuja, to Sir Abubakar Siddiq International Airport (DNSO), Sokoto as RAN2024. The aircraft had earlier completed four flight sectors: Abuja-Kano, Kano-Lagos, Lagos-Kano, and Kano-Abuja, all of which were uneventful.

At 14:35 h, RAN2024 departed DNAA on an Instrument Flight Rules (IFR) flight plan with 55 persons onboard, including 2 flight crew and 2 cabin crew members, with fuel endurance of three hours 24 minutes. The Captain was the Pilot Flying (PF), while the First Officer was the Pilot Monitoring (PM). RAN2024 was cleared to climb and cruise at FL260.

At 14:53:20 h, RAN2024 contacted Kano ACC, and at 14:55:31 h, RAN2024 was cleared to 'SOK' FL260 expect no delay for VOR/DME approach RWY 26 QNH1012 contact time 13:56 standby full met report. Full met report 13:00, wind reported 310/14kt, visibility 10km in nil weather, cloud few at height of 390ft, QNH1012, temperature 33, dew point 20 degrees Charlie. At 14:55:31 h, no objection report released by Kano

At 14:56:20 h, RAN2024 established contact with Sokoto ATC and reported "Persons on board 51 plus 4 crew, endurance three hours from DNAA to DNSO maintaining FL260, estimate 14:30". ATC cleared RAN2024 "SOK FL260 expect no delay for VOR/DME approach runway 26 QNH1012 contact time is 13:56 standby full met. Report".

While cruising at FL260, the flight crew observed a rising oil temperature on Engine Number 1, with indications entering the amber range, accompanied by a decrease in oil pressure.



The crew decided to reduce thrust on the affected engine (engine number 1) to monitor for any improvement, but the temperature and pressure readings continued to fluctuate. The flight crew then executed the Quick Reference Handbook (QRH) for high oil temperature.

At 15:05 h, while at a distance of 100 nm from DNSO on radial 153, maintaining FL260, RAN2024 declared an emergency to Sokoto ATC. Upon the ATC's request for the nature of the emergency, RAN2024 reported smoke from engine number 1. RAN2024 was then asked for their intention. The Flight Crew requested descent, which was granted, and coordination was established with Kano Area Control Centre (ACC) for descent at the Pilot's discretion. While descending through FL250, the crew executed QRH for EMERGENCY/ABNORMAL PROCEDURES (Smoke Evacuation).

According to the Purser, smoke in the cabin was reported by a crew member seated at L2 when a callout was made: "Halon to the aft." The Purser proceeded to the aft section, observed smoke emanating from the cabin floor near seats 24A and 24D, and immediately informed the Captain. The Captain acknowledged the situation, reported that there was also smoke in the cockpit.

The Flight Crew donned their Oxygen Masks. The Cabin Crew also donned their Protective Breathing Equipment (PBE), retrieved a fire extinguisher, and proceeded to the aft section. The Purser confirmed the absence of fire within and outside the lavatory. He also observed the cargo hold through a peephole in the lavatory and found no visible signs of fire. These observations were reported to the Captain. The Captain then informed the Purser that the smoke was originating from Engine number 1 and the aircraft was already in rapid descent. The Cabin Crew reassured passengers of their safety as there was growing panic in the cabin.

During the descent, the flight crew observed indications of Engine number 1 failure.

The Purser contacted the flight crew and reported that the smoke in the cabin had dissipated.



At about 15:14 h, Airport Rescue and Fire Fighting Services (ARFFS) were notified, and three fire service trucks and an ambulance were stationed at strategic locations.

At about 15:26 h, Kano ACC reported loss of radar contact with RAN2024 and requested DATCO to maintain the telephone line to enable continuous monitoring of the situation.

At about 15:27 h, RAN2024 reported 25 nm to Sokoto and was maintaining FL80.

At about 15:28 h, RAN2024 was instructed to continue descent to 3,500ft and cleared for approach to Runway 26.

At about 15:29 h, RAN2024 reported 19 nm.

At about 15:31 h, RAN2024 reported 10 nm and was cleared to land Runway 26, surface wind 320/14kt.

At about 15:35 h, RAN2024 landed DNSO safely, with engine number 1 inoperative.

After landing, the Captain requested ATC to visually inspect the engine area for signs of fire before initiating passenger disembarkation. ATC reported there was no fire.

All persons on board disembarked safely without injuries.

The incident occurred en route to Sokoto at 15:03:55 h, Meteorological conditions prevailed.

1.2 Injuries to persons

| Injuries | Crew | Passengers | Total in the aircraft | Others |
|-----------------|-------------|-------------------|------------------------------|---------------|
| Fatal | Nil | Nil | Nil | Nil |
| Serious | Nil | Nil | Nil | Nil |
| Minor | Nil | Nil | Nil | Nil |
| None | 4 | 51 | 55 | Nil |
| TOTAL | 4 | 51 | 55 | Nil |

1.3 Damage to aircraft

The aircraft sustained no damage.



1.4 Other damage

Nil

1.5 Personnel information

1.5.1 Captain

| | |
|----------------------|---|
| Nationality: | Nigerian |
| Age: | 44 |
| License type: | Airline Transport Pilot License (Aeroplane) |
| License: | Valid till 17 September, 2028 |
| Aircraft ratings: | EMB-135/145 |
| Medical certificate: | Valid till 17 February, 2026 |
| Instrument rating: | Valid till 14 February 2026 |
| Proficiency check: | Valid till 17 August, 2025 |
| Total flying time: | 5242:55 h |
| Total on type: | 4858:30 h |
| Total on type (PIC): | 1640 h |
| Last 90 days: | 262:25 h |
| Last 28 days: | 71:40 h |
| Last 24 hours: | 00:58 h |

1.5.2 First officer

| | |
|---------------|--------------------------------------|
| Nationality: | Nigerian |
| Age: | 29 |
| License type: | Commercial Pilot License (Aeroplane) |



| | |
|----------------------|-----------------------------|
| License: | Valid till 4 April, 2028 |
| Aircraft ratings: | EMB-135/145LR |
| Medical certificate: | Valid till 3 January, 2026 |
| Instrument rating: | Valid till 16 April 2026 |
| Proficiency check: | Valid till 16 October, 2025 |
| Total flying time: | 700 h |
| Total on type: | 511 h |
| Last 90 days: | 132 h |
| Last 28 days: | 36 h |
| Last 24 hours: | 00:58 h |

1.5.3 Purser

| | |
|----------------------|---|
| Nationality: | Nigerian |
| Age: | 44 |
| Licence type: | Cabin Crew Licence |
| Licence: | Valid till 23 July 2027 |
| Aircraft ratings: | EMB-135/145 A340-600 B737-300/500 B747-200 B747-300/400 |
| Medical certificate: | Valid till 29 August 2025 |
| Emergency Drills: | Valid till 21 August, 2025 Evacuation (EMB.135/145) Fire Drill, Ditching |



1.5.3 Engineer 1

| | |
|------------------------|---|
| Nationality: | Nigerian |
| Age: | 36 |
| Licence type: | Aircraft Maintenance Engineer's Licence |
| Licence validity: | Valid till 14 October 2026 |
| Aircraft type ratings: | TB-9 EMB-135/145 LEGACY/600/650 |

1.5.4 Engineer 2

| | |
|------------------------|--|
| Nationality: | Nigerian |
| Age: | 31 |
| Licence type: | Aircraft Maintenance Engineer's Licence |
| Licence validity: | Valid till 2 nd January, 2029 |
| Aircraft type ratings: | EMB-135/145LR LEGACY 600/650 |

1.6 Aircraft information

1.6.1 General information

| | |
|-------------------------------|---------------------------|
| Type: | Embraer EMB-145LR |
| Manufacturer: | Embraer, Brazil |
| Year of manufacture: | 2002 |
| Serial number: | 145628 |
| Certificate of Airworthiness: | Valid till 12 March, 2026 |



Certificate of insurance: Valid till 30 September 2025

Certificate of Registration: Issued 7 March 2022

Total airframe time: 40284:31 h

Total landing cycles: 32363

During a post-occurrence interview, the maintenance engineer who worked on the aircraft after the occurrence stated that a large oil leak was discovered on the center scavenge oil sump transfer to the fairing core oil tube diffuser fittings. The engineer conducted a cleaning of the engine area and then cranked the engine without ignition (motoring), during which another oil leak was observed.

The engineer stated that the source of the smoke was determined to be oil entering the bypass duct, where fan air flows to the pre-cooler and mixes with bleed air from the engine that supplies air to the Environmental Control System (ECS).

1.6.2 Engines

| Engine | Number 1 | Number 2 |
|------------------|-----------------|-----------------|
| Manufacturer | Rolls-Royce, UK | Rolls-Royce, UK |
| Type/Model | AE 3007AIP | AE3007AIP |
| Serial number | CAE312181 | CAE311995 |
| Time Since New | 35388:2 | 37164 |
| Cycles Since New | 30371 | 32515 |

Fuel Used: Jet A1



Figure 1: 5N-BZY after the occurrence.

1.7 Meteorological information

| DNSO | 1200Z | 1300Z | 1400Z | 1500Z |
|-------------|--------------|--------------|--------------|--------------|
| Wind: | 310/12 | 310/09 | 320/14 | 300/05 |
| Visibility: | 9999 | 9999 | CAVOK | CAVOK |
| Weather: | FEW012 | FEW013 | Nil | Nil |
| Cloud: | FEW021CB | Nil | Nil | Nil |



| | | | | |
|-----------|-------|-------|-------|-------|
| Temp/Dew: | 31/21 | 33/20 | 34/20 | 34/20 |
| QNH: | 1013 | 1012 | 1011 | 1010 |

1.8 Aids to navigation

The status of the navigational aids at Abubakar Siddiq International Airport, Sokoto, on the day of the occurrence was as follows:

| | | |
|---------------------------------------|-----------|-------------------|
| "SOK" VOR/DME | 113.9 MHz | - 'Serviceable' |
| "ISK" ILS/DME | 109.5 MHz | - 'Serviceable' |
| ADB Beacon / Binocular | | - 'Serviceable' |
| Wind Direction Indicator/ SATCOM link | | - 'Serviceable' |
| ALDIS Lamp | | - 'Serviceable' |
| Tel lines / CWG Phones | | - 'Serviceable' |
| Digital Clock / MET PC | | - 'Serviceable' |
| Wind Speed Indicator/ AIS Automation | | - 'Unserviceable' |

1.9 Communication

There was effective communication between the Air Traffic Controllers at both Abuja and Sokoto airports with 5N-BZY.

The status of the communication at Abubakar Siddiq International Airport, Sokoto, on the day of the occurrence was as follows:

| | |
|---|-----------------|
| VHF 122.1 MHz Tower Primary Frequency | - 'Serviceable' |
| VHF 124.5 MHz Tower Secondary Frequency | - 'Serviceable' |
| VHF 121.7 MHz Domestic Frequency | - 'Serviceable' |



VHF Intercom Transceiver

- 'Serviceable'

1.10 Aerodrome information

Saddiq Abubakar III International Airport, Sokoto (DNSO) was equipped with a runway designation of 26/08 with an asphalt surface. The length and width of the runway are 3000 meters and 60 meters, respectively. The runway reference point is 125457.2274N 0051224.8324E and an elevation of 308 m (1,010 ft). The aerodrome is located 7km from Sokoto City, Sokoto State.

1.11 Flight recorders

The aircraft is fitted with a solid-state Flight Data Recorder (FDR) and a Cockpit Voice Recorder (CVR) with the following particulars:

| Recorders | Flight Data Recorder | Cockpit Voice Recorder |
|----------------------|-----------------------------|-------------------------------|
| Manufacturer | Honeywell, USA | Honeywell, USA |
| Model | SSFDR | SSCVR |
| Part Number | 980-4700 042 | 980-6022-011 |
| Serial Number | 8873 | 1625 |

The FDR and CVR were retrieved. The FDR was downloaded at the Transportation Safety Laboratory of the Nigerian Safety Investigation Bureau (NSIB), Abuja, Nigeria. The CVR was found to be overwritten.

1.12 Wreckage and impact information

Not Applicable



1.13 Medical and pathological information

Nil

1.14 Fire

There was no fire.

1.15 Survival aspect

Not applicable.

1.16 Test and Research

Nil

1.17 Organization and management information

1.17.1 Rano Air Limited

Rano Air Limited is a Nigerian airline established in 2019 and operates under the oversight of the Nigeria Civil Aviation Authority (NCAA). Rano Air's operations are subject to the provisions of the Nigerian Civil Aviation Regulations (Nig. CARs), and the airline is



required to maintain compliance with applicable safety, maintenance, and crew training standards as prescribed by the NCAA and ICAO Annexes.

The airline holds the required approvals to conduct scheduled and non-scheduled flight operations in Nigeria. It maintains its principal base of operations at Nnamdi Azikiwe International Airport, Abuja.

The company operates a fleet of five Embraer ERJ-145LR aircrafts configured for short-to medium-haul routes. As of the date of the occurrence, the airline provided regular services to several Nigerian destinations, including Abuja, Kano, Lagos, Kaduna, Katsina, Bauchi, Maiduguri, Sokoto, and Osubi.

1.17.2 Nigeria Civil Aviation Authority (NCAA)

NCAA is the government agency saddled with the regulation and oversight of aviation activities in Nigeria. The NCAA was established by the Nigerian Civil Aviation Act (2022) which enables the Director-General of NCAA to make regulations in aviation. The current regulations are as enshrined in the Nigeria Civil Aviation Regulations (Nig. CARs) 2023. Relevant sections of the Nig. CARs guide activities of personnel and service providers in the aviation industry. Oversight activities are achieved by continuous and periodic audits by inspectors of the NCAA.



2.0 FINDINGS

1. The flight crew held a valid licence and were qualified to conduct the flight.
2. The aircraft had a valid Certificate of Airworthiness.
3. While cruising at FL260, the flight crew observed a rising oil temperature and low pressure on Engine number 1 indications.
4. The flight crew donned oxygen masks.
5. The cabin crew donned their Protective Breathing Equipment (PBE) and retrieved a fire extinguisher.
6. The Captain informed the Purser that smoke was originating from Engine number 1.
7. The flight crew declared an emergency.
8. The Purser informed the Flight Crew that the smoke in the cabin had dissipated.
9. The Aircraft landed DNSO safely at about 15:35 h, with engine number 1 inoperative.
10. The Captain requested ATC to inspect for signs of fire before initiating passenger disembarkation.
11. Aerodrome Rescue and Fire Fighting Services (ARFFS) were on standby after notification.
12. The Crew and passengers disembarked safely, without injuries.
13. The FDR and CVR were retrieved.
14. The FDR was downloaded at the Transport Safety Laboratory of the Nigerian Safety Investigation Bureau.
15. The CVR was found to be overwritten.



3.0 IMMEDIATE SAFETY RECOMMENDATION

3.1 Safety Recommendation 2025-003

Nigeria Civil Aviation Authority should invoke part 7 sections 8.1.3 (b) of Nig. Cars, in accordance with legal enforcement action, non-compliant operators with the All Operators Letter (AOL) (NCAA/FSG/AOL/19/03) on continuous overwriting of cockpit voice recorder (CVR) information.

Further Investigation

The Aircraft engine has been prepared for onward shipping for further examination at the OGMA facility in Portugal.



Appendix: Quick Reference Handbook (QRH)

EMERGENCY/ABNORMAL PROCEDURES

Smoke

SMOKE EVACUATION

Condition: Smoke or odor inside the cabin and/or cockpit requiring smoke removal.

| | |
|------------------------|-----------|
| Crew Oxygen Masks..... | DON, 100% |
| Smoke Goggles..... | DON |
| Crew Communication.... | ESTABLISH |

LAND AT THE NEAREST SUITABLE AIRPORT.


Cockpit DoorCLOSE

Reinforced Cockpit Door
Louver Vent
(if applicable)CLOSE

Recirculation Fan.....PUSH OUT

Gasper FanPUSH OUT

Pressurization
Manual Controller1 O'CLOCK
POSITION

WAIT 15
SECONDS

Pressurization Mode
SelectorPUSH IN (MAN)

Passenger OxygenAS REQUIRED

CONTINUES ON NEXT PAGE

S-4

REVISION 16

Copyright © 2000 Boeing. Refer to owner's manual for details.

009-1487113

**EMERGENCY/ABNORMAL PROCEDURES****Smoke****CONTINUED FROM PREVIOUS PAGE****Fuel Pump 1 1B****Fuel Pump 2 2A OR 2C****VTRL PUMP SEL****(if applicable) SET TO B****Battery 1 OFF****Generators 1 and 3 PUSH OUT**Shed Buses, Central DC Bus, DC Bus 1 and
Essential Bus 1 deenergized.**Emergency lights OFF**

| |
|--------------------------------------|
| SMOKE STOPS OR DECREASES? |
|--------------------------------------|

No**Yes****Icing Conditions EXIT/AVOID****SG On Reversionary****Panel 1 PUSH IN****NOTE:** PFD or MFD information is
available in DU 2.**COM 2 on Digital****Audio Panel 2 PUSH IN****Do not set Thrust Lever 1 below idle
in flight.****Monitor fuel quantity indication 1
through FMS.****CONTINUES ON NEXT PAGE****S-10****REVISION 16**

Copyright © by Embraer. Refer to cover page for details.

000-145/1115



EMERGENCY/ABNORMAL PROCEDURES

Non Annunciated

ENGINE HIGH OIL PRESSURE

EICAS Indication: Oil pressure pointer in amber range

OIL TEMPERATURE, OIL LEVEL OR
ENGINE VIBRATION OUT OF LIMITS?

No

Yes

Associated ProcedureACCOMPLISH

END

ENGINE HIGH OIL TEMPERATURE

EICAS Indication: Oil temperature pointer and digits
become red.

Associated Thrust LeverREDUCE

FAILURE PERSISTS?

No

Yes

ABOVE 25'000 FT?

No

Yes

AltitudeMAX 25'000 FT
MINIMUM MEA

FAILURE PERSISTS?

No

Yes

Affected ENGINE FAILURE/SHUTDOWN
Procedure (NAP-19)ACCOMPLISH

END

ENGINE LOW OIL LEVEL

MFD Indication: Oil quantity enters amber range.

Affected ENGINE FAILURE/SHUTDOWN

Procedure (NAP-19)AS REQUIRED

Consider shutting the engine down to preserve oil quantity,
and if required restart it prior to landing.

NOTE: The indication of oil-level is accurate above 3 quarts.

END

ENGINE OIL LOW PRESSURE

EICAS Indication: Oil pressure in amber range.

Associated Thrust LeverREDUCE

Reduce N2 below 88%.

END

NAP-20

REVISION 14

Copyright © by Embraer. Refer to cover page for details.

CRM-140/1115

**EMERGENCY/ABNORMAL PROCEDURES****Smoke****CONTINUED FROM PREVIOUS PAGE**


NOTE: Landing gear lever can not be moved up.

Landing configuration:

Anticipate flap slower actuation.

If landing gear has not been selected down:

**Gear Electrical
OverrideDOORS**

**WAIT 3
SECONDS**

**Gear Electrical
OverrideGEAR/DOORS**

Flaps45°

**V_{REF}V_{REF} 45° +
5 KIAS**

CAUTION: MULTIPLY THE FLAPS
45° UNFACTORED
LANDING DISTANCE BY
1.95.

**Do not actuate Thrust Reverser 2.
Brake effectiveness will be reduced.**

END

**IS SUITABLE
AIRPORT DISTANT?**

No**Yes**

Generators 2 and 4PUSH IN

Battery 2AUTO

CONTINUES ON NEXT PAGE**REVISION 17****S-9**

Copyright © by Embraer. Refer to cover page for details.

User: agodoloff - Printed By myTechCase - Jan 23/23 - 11:13:07

QNH-140/113

**EMERGENCY/ABNORMAL PROCEDURES**

Non Annunciated

ENGINE FAILURE/SHUTDOWN

Condition: Loss of thrust on an engine or abnormal engine indication or precautionary shutdown.

Associated Thrust Lever IDLE

Associated Start/Stop Selector STOP

NOTE: If engine shutdown does not occur, pull the associated fire extinguishing handle.

Engine Thrust Rating CON

APU (if available) START

APU Bleed AS REQUIRED

XBleed AS REQUIRED

Fuel BALANCE

ENGINE RESTART CONSIDERED? No

Yes

Affected ENGINE AIRSTART Procedure (NAP-16) ACCOMPLISH

END

LAND AT THE NEAREST SUITABLE AIRPORT.

TCAS TA ONLY

Altitude MAX 25'000 FT,
MIN MEA

ICING CONDITIONS? No

Yes

XBleed OPEN

Altitude MAX 15'000 FT,
MIN MEA

If it is not possible to descend below 15'000 ft:

Icing Conditions EXIT

ONE ENGINE INOPERATIVE APPROACH AND LANDING Procedure (NAP-30) AS REQUIRED

END

User: agoswin01 - Printed By myTechCare - Jan 23/23 - 11:13:07

ORH-145/1115

REVISION 16

NAP-19

Copyright © by Embraer. Refer to cover page for details.



EMERGENCY/ABNORMAL PROCEDURES

Engine

ENGINE OUT

EICAS Caution: ENG1 (2) OUT

Associated Thrust Lever IDLE

Associated Start/Stop Selector STOP

NOTE: If engine shutdown does not occur, pull the associated fire extinguishing handle.

Engine Thrust Rating CON

APU (if available) START

APU Bleed AS REQUIRED

XBleed AS REQUIRED

Fuel BALANCE

ENGINE RESTART CONSIDERED? No

Yes

Affected ENGINE AIRSTART

Procedure (NAP-16) ACCOMPLISH

END

LAND AT THE NEAREST SUITABLE AIRPORT.

TCAS TA ONLY

XBleed OPEN

Altitude MAX 25'000 FT,
MIN MEA

ICING CONDITIONS? No

Yes

Altitude MEA OR
15'000 FT,
WHICHEVER IS
HIGHER

If it is not possible to descend below 15'000 ft:

Icing Conditions EXIT

ONE ENGINE INOPERATIVE
APPROACH AND LANDING

Procedure (NAP-30) AS REQUIRED

END

User: agowinot - Printed By myTechCare - Jan 23/23 - 11:13:07

EAP 6-10

REVISION 14

4-145/1113

**EMERGENCY/ABNORMAL PROCEDURES****Smoke****SMOKE / FIRE / FUMES**

Condition: Smoke, fire or fumes visually confirmed or identified by odor without an EICAS warning.

Crew Oxygen Masks.....DON, 100%

Smoke Goggles.....DON

Crew Communication....ESTABLISH

LAND AT THE NEAREST SUITABLE AIRPORT.

Recirculation Fan.....PUSH OUT

Gasper Fan.....PUSH OUT

NOTE: Any time smoke becomes dense, perform **SMOKE EVACUATION Procedure(S-4).**

SMOKE ORIGIN IS OBVIOUS AND CAN BE REMOVED?

No

Yes

Affected SourceREMOVE

SMOKE STOPS OR DECREASES?

No

Yes

SMOKE EVACUATION Procedure (S-4).....AS REQUIRED

END

Cabin CrewNOTIFY

FSTN Belts.....ON

CONTINUES ON NEXT PAGE

S-6

REVISION 16

Copyright © by Embraer. Refer to owner page for details.

GRH-145/115

**EMERGENCY/ABNORMAL PROCEDURES****Smoke****CONTINUED FROM PREVIOUS PAGE****Landing configuration:**

Emergency lights.....ON

Flaps45°

V_{REF}V_{REF} 45°**END**

Icing Conditions.....EXIT/AVOID

AirspeedMAX 250 KIAS

SG On Reversionary

Panel 2.....PUSH IN

NOTE: PFD or MFD information is available in DU 4.

COM 1 on Digital

Audio Panel 1.....PUSH IN

Do not set Thrust Lever 2 below idle in flight.

Monitor fuel quantity indication 2 through FMS.

Relevant Inoperative Items:

| | |
|------------------------------------|----------------------------|
| ADF 2/DME 2/VOR 2/VHF 2/ILS 2/MB 2 | |
| Audio System 2 | ISIS/Standby Altimeter |
| Brakes Inbd | RMU 2 |
| DU 2 and 5 | Standby Attitude Indicator |
| FMS 2 | Steering |
| Ground Spoiler Inbd | Transponder 2 |

NOTE: Landing gear lever can not be moved up.

CONTINUES ON NEXT PAGE**S-12****REVISION 16**

Copyright © by Embraer. Refer to owner's manual for details.

CNR-1467115


**EMERGENCY/ABNORMAL PROCEDURES****Engine****ENGINE OIL LOW PRESSURE**

EICAS Warning: E1 (2) OIL LOW PRESS may be presented.

EICAS Indication: Oil pressure may be red.

Associated Thrust Lever..... REDUCE

Reduce Thrust Lever to at least N2 below 88%, until pressure is within limits.



G91-149/1115

REVISION 14

Copyright © by Embraer. Refer to owner page for details.

EAP 6-7

**EMERGENCY/ABNORMAL PROCEDURES****Smoke****CONTINUED FROM PREVIOUS PAGE****DESIRED
EVACUATION RATE?****Fast****Normal**

**Pressurization Manual
ControllerAS REQUIRED**
Turn the controller clockwise towards
UP to adjust desired evacuation rate.

END

**Pressurization Manual
ControllerUP**
Packs 1 and 2PUSH OUT
Bleeds (at least one)....PUSH IN
**Altitude10'000 FT OR
MEA,
WHICHEVER
IS HIGHER**

**Recover cabin pressure as soon as
smoke has been cleared.**

**EMERGENCY DESCENT
Procedure (NAP-6)....AS REQUIRED**

END

CRM-1459118

REVISION 16

Copyright © by Endstream. Refer to owner page for details.

S-5

**EMERGENCY/ ABNORMAL PROCEDURES****Smoke****CONTINUED FROM PREVIOUS PAGE****Relevant Inoperative Items:**

| | |
|------------------------------------|----------------------|
| ADF 1/DME 1/VOR 1/VHF 1/ILS 1/MB 1 | |
| Audio System 1 | Ground Spoiler Outbd |
| Autopilot | Main Pitch Trim |
| Brakes Outbd | RMU 1 |
| DU 1 and 4 | Speed Brake |
| FMS 1 | Transponder 1 |

NOTE: Landing gear lever can only be moved up using downlock release button (DN Lock Rel).

Landing configuration:

Anticipate flap slower actuation.

Emergency lightsON

Flaps45°

V_{REF}V_{REF} 45° + 5 KIAS

CAUTION: MULTIPLY THE FLAPS 45° UNFACTORED LANDING DISTANCE BY 1.95.

Do not actuate Thrust Reverser 1.

Brake effectiveness will be reduced.

END

Generators 1 and 3PUSH IN

Battery 1AUTO

Backup BatteryPUSH OUT

WARNING: CONSIDER AN IMMEDIATE LANDING.

CONTINUES ON NEXT PAGE

REVISION 17

S-11

Copyright © by Embraer. Refer to cover page for details.

User: agodwin01 - Printed By myTechCare - Jan 23/23 - 11:13:37

09H-1401115

**EMERGENCY/ABNORMAL PROCEDURES**

Non Annunciated

ENGINE OVERTEMPERATURE

Condition: ITT pointer and digits flashing amber or red.

Associated Thrust Lever.....REDUCE

ITT INDICATION WITHIN LIMITS? No

Yes

Operate at reduced thrust to keep ITT within limits.

END

Associated Bleed.....PUSH OUT

Altitude.....MAX 25'000 FT,
MIN MEA

ITT INDICATION STILL OUT OF LIMITS? No

Yes

ENGINE FAILURE/SHUTDOWN

Procedure (NAP-19).....ACCOMPLISH

END

Operate at reduced thrust to keep ITT within limits.

TCAS.....TA ONLY

END

ENGINE TAILPIPE FIRE

Condition: Tailpipe fire was detected visually by crew or ground personnel. No EICAS message displayed.

Affected engine:

Thrust Lever.....IDLE

Start/Stop Selector.....STOP

Ignition.....OFF

Fuel Pump.....OFF

XFeed Selector Knob.....OFF

Start/Stop Selector.....START, THEN RUN

ITT.....MONITOR

ATC.....NOTIFY



WAIT 90 SECONDS

Associated Start/Stop Selector.....STOP

Associated

Fire Extinguishing Handle.....PULL (DO NOT
ROTATE)NOTE: If fire is not extinguished while the engine is motored,
ground personnel support must be requested.

END

REVISION 14

NAP-21 |

094-145/1115

Copyright © by Embraer. Refer to owner page for details.