

## INTERIM STATEMENT

APL/2019/07/23/INTR/06

## **Nigerian Safety Investigation Bureau**

Interim Statement on the Accident involving Boeing 737-300 aircraft operated by Air Peace Limited with nationality and registration marks 5N-BQO, which occurred on Runway 18R at Murtala Mohammed International Airport, Lagos State, Nigeria on 23 July 2019.

**Report number:** APL/2019/07/23/INTR/06

**Report format:** Interim Statement

Published: 23 July 2025

On 23 July 2019 at 10:38 h, a Boeing 737-300 aircraft with nationality and registration marks 5N-BQO departed Port Harcourt for Lagos with 133 persons on board and six (6) crew members, as APK7191. The Co-pilot was the Pilot Flying (PF) and the Captain was the Pilot Monitoring (PM). The flight operated on an Instrument Flight Rules (IFR) flight plan.

At 11:26:12 h, the Control Tower (CT) gave APK7191 final landing clearance as "APK7191 exercise caution, runway surface wet, wind 290°/06 kt runway 18R cleared to land which the crew acknowledged. The Captain reported noticing that the aircraft was not aligned with the runway centerline during final landing callouts: 50, 30, and took control while announcing, "I have controls" and "correcting back to the centerline". The crew stated that "the right wheel touched down simultaneously, we lost visibility, and the nose wheel touched down." The aircraft landed on the nose gear, causing the nose wheel to break off.

At 11:28:43, APK7191 requested a tow truck, and upon further inquiry from CT, the flight crew responded that the gear had collapsed. At 11:45:33 h, APK7191 requested ground equipment to disembark passengers. The conveyance vehicle and moveable passengers' stairs arrived shortly afterwards, and the passengers disembarked the aircraft without injuries. The accident occurred in daylight and in rain.

## **ACTION**

The final report has been completed. The investigation has received the manufacturer's analysis of the FDR raw data and is currently being finalized for release to the public which is in line with the requirements of Section 6.3 of the International Civil Aviation Organization (ICAO) Annex 13 to the Convention.

This interim report is being issued on the 6th anniversary of the Accident in accordance with the provisions of Annex 13 to the Convention on International Civil Aviation.

In accordance with Annex 13 to the Convention on International Civil Aviation, Nigerian Safety Investigation (Establishment) Act 2022, Civil Aviation (Investigation of Air Accident and Incidents) Regulations 2023, the objective of this investigation is to prevent aviation accidents and serious incidents. It is not the purpose of any such investigation and the associated investigation report to