



INTERIM STATEMENT
IAC/2014/03/27/INTR/01

Accident Investigation Bureau

Interim statement on the serious incident involving
International Aviation College Diamond DA-40D aircraft
with nationality and registration marks 5N-BRM at Ilorin
International Airport, Ilorin, Kwara state
on 27th March, 2014

AIB REPORT No.: IAC/2014/03/27/INTR/01

REPORT FORMAT: INTERIM STATEMENT

PUBLISHED: 27TH MARCH, 2019

On the 27th March, 2014, at about 10:26 h, a Diamond DA-40D aircraft owned and operated by International Aviation College, with nationality and registration marks 5N-BRM was on a check-out training flight with a student pilot and an instructor. The student executed two landings under supervision of the instructor and was thereafter released for his first solo flight. The student pilot executed a successful Touch and Go exercise, after which he requested for a full stop landing and ATC granted approval to his request.

At 11:17 h the student pilot reported finals on runway 23 for a full stop landing and was cleared to land. The aircraft touched down on runway 23, bounced twice, and then veered off the runway to the left into the bush.

The aircraft was substantially damaged.

The Draft Final report review is ongoing following which, the report will be sent to stakeholders for their substantial comments in line with the requirements of section 6.3 of International Civil Aviation Organization (ICAO) Annex 13 to the convention.